

Capitol, Havana / Cuba



© Rostislav Ageev - Fotolia.com Rostislav Ageev - Fotolia.com

Reference data

- **Building activity**
Façade restoration / render , Façade restoration / natural stone
- **Object type**
Historically protected / historically valuable buildings , Office and administration buildings , City halls
- **Object address**
, Havana/La Habana
- **Date / Completion**
2019
- **Client**
Dr. Eusebio Leal Spengler
- **Architect**
Hendrik Romstedt
- **Contractor**
Michael Diegmann
- **Viewing possible?**
No

Description

The Capitol of Havana was built in 1929 and inaugurated on 20 May that year. Until 1959 it served as the seat of the legislature. The area where the Capitol is located was originally a swamp area and was used during the Spanish colonial period, first to house slaves and then as a botanical garden. The Capitol was built between 1926 and 1929. In 2010 the extensive, complex renovation of the building began. Since March 2018, visitors have again been granted access to the building. The last renovation work is expected to be completed by the time of the celebrations for the 500th anniversary of the founding of the city in November 2019. The Cuban parliament will soon move back into the building.

Problem

The façade has been heavily soiled over the last 90 years. The sun of the island state in the Caribbean also severely affected the façade. The aim of the restoration was to preserve the original structure and colour scheme. The renewed absorption of water and pollutants should be prevented.

Product systems / sizes used**› Arte Mundit**

Art. No. 222020

**› Glass Powder**

Art. No. 5280

**› Funcosil FC**

Art. No. 0711

**› Color LA Fill Historic**


Art. No. 6471

**Impressions**

©



©



©

Reference



Further information can be found on:

https://www.remmers.co.uk/en_GB/referenceDetail/905