Volkswagen Arena, Wolfsburg (DE)



© Remmers Gruppe AG Remmers Gruppe AG

Reference data

- **Building activity**
  Floor coating , Floor coating - anti-slip systems , Floor coating - decorative systems
- **Object type**
  Stadiums / arenas / sport facilities
- **Object address**
  , 38446 Wolfsburg
- **Date / Completion**
  2009
- **Contractor**
  Drewitz GmbH
- **Viewing possible?**
  Yes

Description

Football stadiums welcome thousands of visitors every couple of weeks or more. It is therefore vital to give the football fans a sturdy, non-slip floor under their feet, For this reason, a new floor coating that meets these requirements was applied at the Volkswagen Arena in Wolfsburg.

Problem

The old coating had visible signs of wear due to damaged sealant, and had come detached from the substrate in some areas. A new floor coating with a slip resistance rating of R11 was applied, and was sprinkled with colour flakes to create contrast.

Product systems / sizes used

› Epoxy BS 2000
Art. No. 6001



› Epoxy BS 3000 M
Art. No. 6370



› Epoxy Flex PH
Art. No. 6250




› Add 250
Art. No. 6271




› Color Flakes
Art. No. 6461




Impressions



©



©



©



©

Further information can be found on:

https://www.remmers.co.uk/en_GB/referenceDetail/31682